## **GTEC Inactive Ash Basin - Weekly Inspection Form**

MONTH: April 2019
Inspection Date: 4-1-19 4-5-19 4-11-19 4-17-19 4-28-19
Inspector: (name) S. GROVER S. GROVER

Form Prepared by: ERM NC, Inc. For Use by: Grand Tower Energy Center, LLC File 230.0319



INSPECTION ITEM	PROBLEM FOUND (Y OR N)	DESCRIBE PROBLEM	E ONLY IF PROBLEM FOUND  DESCRIBE  CORRECTIVE  ACTION TAKEN	DATE OF CORRECTIVE ACTION	INSPECTOR INITIALS							
Inspect for any appearances of actual or potential structural weakness												
Inspect for visual indications of erosion; formation of rills or guilies; along interior and exterior slopes		V	N	13	2							
Inspect for visual indications of surface soll "sluffing" or sliding along interior and exterior slopes		Ν	7	N	h							
Inspect vegetation height; should be maintained less than 6-inches and no woody vegetation (tree) growth.		Ν	2	N	N							
Inspect for visual indications of animal burrowing activities along interior and exterior slopes.		NOTE 1	7	NOTE !	4							
Inspect the discharge of all outlets of hy		which pass through	h the basin dike fo	r abnormal discolo	ration, flow or dis-	charge of debris or sediment.						
Outfall at south end of basin; inspect for visual signs of discoloration of discharge water. If no discharge is observed, place "N/A" in Problem Found Column.	/	NA	MA	P/A								
Outfall at south end of basin; inspect for visual signs of sedimentation from discharge. If sediment is observed, describe color and texture of sediments.	1	Ŋ	2	2								
Visually inspect the outfall structure at the south end of the basin for structural distress or related operational issues.		Ν	V	N								

ADDITIONAL NOTES																	
NOTE 1 -	WEST	STOE	OF	LENEE	HAS	A	POINT	~2 FT	WIDE	WASAES	OUT	FROM	THE LEVEE	ABOUT	3 FT 7	·al	
•	NOT	SEEN 1	N 41												- 1 . 3		
	FORNO	ON 4/	17														
	4/28	LATE	INSPE	CHION	DUE	70	BAIN	POIN	F	WASH OUT	SOT	N LETT	le wider	BUT NO	DEBLER	JUTO	LEVEE